

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region III - 6th & Walnut Sts.
Philadelphia, Pa. 19106

ORIGINAL
(Red)

*Greg
P. Linder*

SUBJECT: Llangollen Landfill

DATE: March 7, 1977

FROM: Charles L. Kleeman *Charlie*
Technical Assistance Section-3WA30

TO: Larry S. Miller, Chief *LSM*
Water Quality Monitoring Office-3SA60

THRU: Bernard D. Sarnoski, Chief *BDS*
Technical Assistance Section-3WA30

Concerning the next phase of sampling of wells near the Llangollen Landfill, the Water Supply Branch requests that you take samples from the following wells.

- a. Monitoring Well #49 (This is the well that did not get sampled on February 22, 1977.) This is a 4 inch well. Depth to water surface is 85 feet. No pump in well.
- b. Monitoring Well #25 This is a 6 inch well. Depth to water surface is 76 feet. No pump in well.
- c. Monitoring Well #22 This is a 6 inch well. Depth to water surface is 79 feet. No pump in well. Water-level recorder installed on well.

For the above three monitoring wells (#49, #25, #22) please do a GC/MS scan and quantify identified organics.

Please note the depth to water level in these wells (85 feet, 76 feet, and 79 feet); and arrange for the sampling crew to bring along their submersible pump and sufficient length of cable and hose.

Also, I must remind you that we still want you to collect a sample for heavy metals analysis from Monitoring Well #42. This was in my earlier request memorandum of January 24, 1977; however, I don't believe that such a sample was collected on February 22, 1977.

Again I must emphasize that I will need at least a week's notice in advance of the date and time selected for this sampling in order that the necessary arrangements can be made for access to wells, removal of recorders, and to have a representative of Delaware D.N.R./D.E.C. present to help locate the wells.

AR100338